Installation plan, dimensions of the machine

Basic machine



A Setting screws (8) resp. levelling elements (4) (see "Installation criteria" in this chapter)

B Bores ø18x120 (dia. 0.709"x4.72") for anchor bolts

Space for operation

Space for maintenance

Machine with bar loader FMB and chip conveyor



Machine with bar loader LM-800 and chip conveyor

